

Assessment of the condition of underground collector lines


situated inside the technological complexes of
underground storage facilities

Agenda

- General information
- Reasons , methodology, planning, execution
- Details from inspection
- Results

Underground gas storage Lab

- 30 years of a solid track record
- Located in the south-western part of Slovakia
- Technical infrastructure
 - Central station
 - Dispatching center
 - Compressor fleet including 8 centrifugal compressors
 - Gas metering
 - Piping and gas collector lines
 - Gathering stations and pipelines



Underground gas storage Lab



Gas collector lines at Central station

- 9 gas collector lines for wet or dry gas
- Nominal diameter from 500 to 700 mm
- Design pressure from 40 to 100 bars
- Age from 20 to 25 years
- Length 13 to 140 m
- Installed either at concreted trenches or buried



Reasons for gas collector lines assessment

- Importance for storage facilities operation
- Age in the middle of their life-cycle
- No specific methodology set by authorities
- Unfavoured access as the most are collectors are buried
- No cathodic protection of buried lines within Central station

All these facts represented unacceptable risk, which forced us to set up **a project aimed at definition of remaining useful life of gas collector lines**

Methodology

1. Pressure tests

- Statement on current status
- Additional stress at spots with wall thickness losses, affected by corrosion or defects
- No prediction of remaining lifetime


2. Non destructive testing (NDT)

- General perspective of collectors conditions
- Data for forecasting useful life and future inspection program
- However, requires an extensive preparation (excavation, modification, cleaning...)


Planning

Specifically tailored inspection program was processed in close co-operation with external suppliers for every gas collector line split into the following:

- Technical program
- Preparation works
 - Excavations
 - Modifications
 - Cleaning
- Inspection
- Data evaluation
- Contingency planning
- Repairs (if needed)



Time schedule



Inspection of collectors K 102, K 103



K 102

Nominal diameter 700 mm

Length 57 m

Nominal pressure 10 MPa

K 103

Nominal diameter 700 mm

Length 26 m

Nominal pressure 10 MPa

Findings on collectors K 102, K 103

- **No serious defects were revealed**
- Only lamination defects (mill defects), originating from manufacturing process were found
- There were no relevant indications of internal and external corrosion
- There was not an immediate risk for safety of operation
- However, lamination parts were reinforced by installation of ‘hot sleeves’
- **Based on simulation, safe operation forecasted until year 2025**
- The next inspection with assessment planned 2025

Repairing of collectors K 102, K 103



Inspection of collectors K 100, K 101

K 100

Nominal diameter 700 mm

Length 136 m

Nominal pressure 10 MPa

K 101

Nominal diameter 700 mm

Length 105 m

Nominal pressure 10 MPa



Inspection of collectors K 100, K 101

- Excavation and preparation for bends' installation
- Inspection of all off-takes
- Material shop preparation
- Modifications of collectors' entries
- Ultrasonic in-line inspection by an external company



Inspection of collectors K 100, K 101






Inspection of collectors K 100, K 101




Findings on collectors K 100, K 101



- **No serious defects were revealed**
- Only lamination defects (mill defects), originating from manufacturing process were found
- Lamination parts were reinforced by installation of ‘hot sleeves’
- **Based on simulation, safe operation forecasted until year 2015, the next inspection with assessment planned 2015**



Findings on collectors K 100, K 101



Analysis of material stress



Repairing of collectors K 100, K 101



Lessons learned


- Gas collector lines installed at concreted trenches were more defected than those buried ones

- No release detected from gas collector lines

- Defects only from the manufacturing process

- No corrosion was detected inside

- Minimal degradation of material



Contacts

Stanislav Rehak,

NAFTA a.s., Naftarska 965
908 45 Gbely
Slovakia

mob. +421 905 352795
E-mail: stanislav.rehak@nafta.sk

Anton Misany

NS a.s. Gbely, Naftarska 1413
908 45 Gbely
Slovakia

mob. +421 905 707987
E-mail: anton.misany@naftastroj.sk

Ladislav Goryl,

NAFTA a.s., Naftarska 965
908 45 Gbely
Slovakia

mob. +421 905 843176
E-mail: ladislav.goryl@nafta.sk